

RECEIVED

STATE OF COLORADO

Revised 02/03

CORRES. CONTROL
INCOMING LTR NO.

00319 RF03

DUE DATE
ACTIONBill Owens, Governor
Douglas H. Benevento, Executive Director

Dedicated to protecting and improving the health and environment of the people of Colorado

4300 Cherry Creek Dr. S. Laboratory and Radiation Services Division
Denver, Colorado 80246-1530 8100 Lowry Blvd.
Phone (303) 692-2000 Denver, Colorado 80230-6928
TDD Line (303) 691-7700 (303) 692-3090
Located in Glendale, Colorado<http://www.cdphe.state.co.us>Colorado Department
of Public Health
and Environment

DIST.	LTR	ENC
BERARDINI, J. H.	X	
BOGNAR, E. S.	X	
CROCKETT, G. A.		
DECK, C. A.	X	
DEGENHART, K. R.		
DIETER, T. J.		
DIETERLE, S. E.		
FERRERA, D. W.	X	
FERRI, M. S.		
GERMAIN, A. L.		
GIACOMINI, J. J.		
ISOM, J. H.		
LINDSAY, D. C.	X	
LONG, J. W.		
LYLE, J. L.		
MARTINEZ, L. A.	X	
NAGEL, R. E.	X	
NORTH, K.	X	
PARKER, A. M.	X	
POWERS, K. P.		
RODGERS, A. D.		
SHELTON, D. C.	X	
SPEARS, M. S.		
TRICE, K. D.		
TUOH, N. B.	X	
WILLIAMS, J. L.		
PARSONS, D.	X	
BUTLER, L.	X	
FREIBOTH, C.	X	
NESTA, S.	X	
BROOKS, L.	X	

COR. CONTROL	X
ADMN. RECORD	X
PATS/130	

Reviewed for Addressee
Corres. Control RFP4/3/03
Date By

Ref. Ltr. #

DOE ORDER #

5400-1

March 27, 2003

Mr. Richard DiSalvo

Acting Assistant Manager for Environment and Stewardship

U.S. Department of Energy, Rocky Flats Field Office

10808 Highway 93, Unit A

Golden, CO 80403-8200

RE: Reconnaissance Level Characterization Report (RLCR) for Buildings 308B and 308D - Concurrence


Dear Mr. DiSalvo:

The Colorado Department of Public Health and Environment, Hazardous Materials and Waste Management Division has reviewed the RLCR for Buildings 308B & D, Revision 0 dated January 21, 2003, received on February 13, 2003. Based on the information contained in the RLCR and the additional sampling results provided on March 26, 2003, we are hereby concurring with the determination that Buildings 308B and 308D are Type 1 Facilities.

Although we are concurring that these are Type 1 facilities, D&D should coordinate the demolition plans with ER, especially for the demolition of B308D. It is indicated that B308D has a 15-foot deep sump. Due to this sump being in an erosion sensitive area, and possible re-contouring of this area, the depth of removal may need to exceed the expected three-foot minimum. As such, the final D&D removal activities should be coordinated with ER to properly address this concern.

If you have any questions regarding this correspondence please contact me at (303) 692-3367 or David Kruchek at (303) 692-3328.

Sincerely,


Steven H. Gunderson
RFCA Project Coordinator

cc: Steve Tower, DOE
Tim Rehder, EPA
Duane Parsons, KH
Lane Butler, KH

Cameron Freiboth, KH
Dave Shelton, KH
Steve Nesta, KH
Administrative Records Building T130G


APR 2003
RECEIVED
RECORDS CENTER

ADMIN RECORDS

BZ-A-000580